Converting Sines to Cosines $100sin(500t) = 100cos(500t - 90^{\circ})$

 $100cos(500t) = 100sin(500t + 90^{\circ})$